

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)


1. Name of the Officer LEKSHMI MOHANLAL
2. Name of the School MAM Model School, Metca Land, Chavarcode
3. Location with name of Education District / Sub.District Attingal / Varkala
4. Classification of Building as specified in column 4 of the application for fitness certificate and size Permanent Three storied RCC roof Building
3* 47.21* 9.79* 3.00m
3* 30.67* 9.35* 3.00m
5. Period for which the certificate is issued 2023-24
6. Nature of defects, if any
a) Foundation and basement
b) Superstructure
c) Doors and Windows
d) Wood work wrought and put up
e) Roof
f) Flooring
g) Miscellaneous (Cracks, etc.) } NIL
7. Any major defects noticed which will render the building unsafe in any manner : NIL
8. Whether maintenance works have been done properly : Yes
9. Whether the structure is sound or not for conducting classes : Sound under normal wind and weather condition

CERTIFICATE

Certified that the school building was inspected by me on 16.06.2023 and found to be fit to conduct classes for the period 2023-24 academic year under normal weather conditions for the reasons stated above

Place: Elakamonn

Date: 16.06.2023




**CHAIRMAN
METCA**
Metca Land, Chavarcode
Palayamkundu P.O., Varkala
Pin: 695 146




Dr. N. PRABALA CHANDRAN
Principal

M.A.M Model Senior Secondary School
CBSE No: 930383, School No: 75327
Chavarcode, Palayamkundu P.O, TVM